

# Forney

## EASY WELD™

**WARNING:** To prevent serious injury, read manual warnings and instructions before use.

### 100 ST WELDER QUICK START GUIDE


#### TIG

- 1** Attach a size 25 Dinse TIG torch  
(Size 9 or 17 with valve is recommended)
- 2** Verify proper shielding gas is used for TIG welding. (100% Argon)
- 3** Make sure process switch is on TIG
- 4** Adjust amperage
- 5** Open gas valve on torch and use lift arc technique




### TIG WELDING TIPS

#### OPTIMAL ARC LENGTH



- Optimal arc length varies by electrode type and diameter but is approximately 1/16"

#### ARC START




- A scratch or lift Start is often used to initiate the arc
- Try to minimize electrode and tungsten contamination

#### AMPERAGE



- Affects penetration and bead width
- Amperage is often referred to as "heat" in TIG Welding

#### TRAVEL SPEED



- Affects bead width and height
- Can also affect penetration

**WARNING:** To prevent fire and serious injury: Keep torch and wire clear of grounded objects while welder is plugged in. Be sure to follow safe welding procedures and wear proper PPE (clothes, welding helmet, safety glasses, welding gloves, boots, etc.)

# Forney

## EASY WELD™

**WARNING:** To prevent serious injury, read manual warnings and instructions before use.

### 100 ST WELDER QUICK START GUIDE

#### STICK


- 1** Plug in welder
- 2** Adjust polarity for the stick electrode (Usually DCEP - Electrode Positive)
- 3** Make sure process switch is on STICK
- 4** Adjust amperage per electrode manufacturers recommendations



GENERAL AMPERAGE RECOMMENDATION			
Ø	E6011, E6013, E7014	E7018	E308, E309, E316, E312
1/16"	30-40A	N/A	20-40A
5/64"	40-60A	N/A	30-50A
3/32"	50-70A	70-80A	40-70A
1/8"	80A	80A (DIFFICULT)	50-80A


### STICK WELDING TIPS

#### OPTIMAL STICKOUT



- Optimal stickout varies by electrode type and diameter but is approximately 1/16"

#### STRIKE ARC




- Scratch or tap technique is often used

#### AMPLERAGE



- Affects penetration and bead width
- Can also affect spatter, electrode starting and ability to weld vertical or overhead

#### TRAVEL SPEED



- Affects bead width and height
- Can also affect penetration